

NPI MISSOURI INC

636-940-1005 clientcare@npimo.com http://www.npimo.com



RESIDENTIAL REPORT

11821 Co Rd 3410 Saint James MO 65559

Trophy Properties
JUNE 24, 2021



Inspector
Robert Gould
ASHI #205896, Qualified MO Septic
Inspector #50581
636-940-1005
clientcare@npimo.com



Agent
Phil Brown
Trophy PA--Ballwin
(314) 753-7444
philbrown@trophypa.com

11821 Co Rd 3410

TABLE OF CONTENTS

1: Inspection Details	5
2: Structural Components	6
3: Exterior	10
4: Roofing	15
5: Plumbing	20
6: Electrical	24
7: Heating	27
8: Air Conditioning	28
9: Interiors	30
10: Built-in Appliances	34
11: Insulation and Ventilation	35
12: Fireplaces and Fuel-Burning Appliances	36
13: Swimming Pool	37
Standard of Practice	39

NPI Missouri Inc Page 2 of 40

SUMMARY





2.1.1 Structural Components - Foundation, Basement & Crawlspaces: Limited visibility

2.1.2 Structural Components - Foundation, Basement & Crawlspaces: Water Intrusion

2.2.1 Structural Components - Floor Structure: Termite Intrusion

2.2.2 Structural Components - Floor Structure: Improper Installation

3.4.1 Exterior - Decks, Balconies, Porches & Steps: Wood to Earth Clearance

3.5.1 Exterior - Vegetation, Grading, Drainage & Retaining Walls: Tree Overhang

3.5.2 Exterior - Vegetation, Grading, Drainage & Retaining Walls: Trim Vegetation

3.6.1 Exterior - Walkways, Patios & Driveways: General Deterioration-Asphalt

3.6.2 Exterior - Walkways, Patios & Driveways: Cracking and Settling

○ 4.1.1 Roofing - Coverings: Beyond Design Life

○ 4.2.1 Roofing - Roof Drainage Systems: Downspouts Drain Near House

• 4.2.2 Roofing - Roof Drainage Systems: Damaged/Filled with Debris

○ 4.2.3 Roofing - Roof Drainage Systems: Damaged downspout

○ 4.3.1 Roofing - Flashings: Replace

5.2.1 Plumbing - Drain, Waste, & Vent Systems: Improper Installation - S-Trap

5.2.2 Plumbing - Drain, Waste, & Vent Systems: Leaks

○ 5.4.1 Plumbing - Water Heater: Improper Installation

⚠ 6.3.1 Electrical - Sub-Panel: Panel Location

6.4.1 Electrical - Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage: Exposed Ends & Splices

6.4.2 Electrical - Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage: Loose Wiring

○ 6.7.1 Electrical - GFCI & AFCI: No GFCI Protection Installed

○ 8.1.1 Air Conditioning - Cooling Equipment: Insulation missing or damaged

⚠ 9.1.1 Interiors - Walls: Damaged Fire Barrier

⚠ 9.1.2 Interiors - Walls: Visible Mold

○ 9.1.3 Interiors - Walls: Improper material

○ 11.3.1 Insulation and Ventilation - Exhaust Systems: Dryer Vents Into Attic

NPI Missouri Inc Page 3 of 40

- 12.2.1 Fireplaces and Fuel-Burning Appliances Chimney & Vent Systems: Cleaning
- 13.1.1 Swimming Pool Pool Maintenance: Required Pool Maintenance

NPI Missouri Inc Page 4 of 40

1: INSPECTION DETAILS

Information

Occupied

Occupied, Furnished

Type of Building

Single Family

StyleRanch

Weather Conditions

Dry, Cloudy

Temperature (approximate)

72 Fahrenheit (F)

NPI Missouri Inc Page 5 of 40

2: STRUCTURAL COMPONENTS

		IN	NI	NP	0
2.1	Foundation, Basement & Crawlspaces	Χ			Χ
2.2	Floor Structure	Χ			Χ
2.3	Wall Structure	Χ			
2.4	Ceiling Structure	Χ			
2.5	Roof Structure & Attic	Χ			

NP = Not Present

O = Observations

Information

Foundation, Basement & **Crawlspaces: Foundation**

Concrete

Floor Structure: Sub-. oor

Plywood

Roof Structure & Attic: Type

Gable

Roof Structure & Attic: Material

Plywood

Floor Structure:

Basement/Crawlspace Floor

Concrete

Wall Structure: Material

Wood

Floor Structure: Material

Dimensional Lumber

Ceiling Structure: Material

Wood







Observations

2.1.1 Foundation, Basement & Crawlspaces

LIMITED VISIBILTY

BASEMENT

Visibility of foundation was extremely limited due to finish material.



NPI Missouri Inc Page 6 of 40



2.1.2 Foundation, Basement & Crawlspaces


WATER INTRUSION

NORTHWEST CORNER

Water intrusion is evident in the foundation wall at the Northwest corner. Recommend further evaluation by a waterproofing contractor.

Recommendation

Contact a qualified professional.



2.2.1 Floor Structure

TERMITE INTRUSION

BASEMENT




NPI Missouri Inc Page 7 of 40

Evidence of termite intrusion is present at the rear wall. No visible damage was present at the time of the inspection. See separate termite report for recommended treatment.

Recommendation

Contact a qualified professional.



2.2.2 Floor Structure

IMPROPER INSTALLATION


SUPPORT POST

Support posts for the central beam are not on footings and not secured to the beam.

Recommendation

Contact a qualified professional.







NPI Missouri Inc Page 8 of 40



NPI Missouri Inc Page 9 of 40

3: EXTERIOR

		IN	NI	NP	0
3.1	Siding, Flashing & Trim	Χ			
3.2	Eaves, Soffits & Fascia	Χ			
3.3	Exterior Doors	Χ			
3.4	Decks, Balconies, Porches & Steps	Χ			Χ
3.5	Vegetation, Grading, Drainage & Retaining Walls	Χ			Χ
3.6	Walkways, Patios & Driveways	Χ			Χ

Information

Inspection Method

Visual, Attic Access

Exterior Doors: Exterior Entry Door

Steel

Decks, Balconies, Porches &

Steps: Material

Wood

Walkways, Patios & Driveways:

Flatwork Material Concrete, Asphalt

Siding, Flashing & Trim: Siding MaterialBrick Veneer, Wood, Metal, Fiber Cement











NPI Missouri Inc Page 10 of 40

Decks, Balconies, Porches & Steps: Appurtenance

Deck





Observations

3.4.1 Decks, Balconies, Porches & Steps


WOOD TO EARTH CLEARANCE

DECK



Recommendation

Contact a qualified professional.







3.5.1 Vegetation, Grading, Drainage & Retaining Walls


TREE OVERHANG

ROOF

Trees observed overhanging and in contact with the roof in several areas. Conditions may result in damaged roof components.

Recommendations

NPI Missouri Inc Page 11 of 40



3.5.2 Vegetation, Grading, Drainage & Retaining Walls



TRIM VEGETATION

EXTERIOR

Trim vegetation away from the exterior walls.



3.6.1 Walkways, Patios & Driveways

GENERAL DETERIORATION-ASPHALT

Keep cracks filled and surface sealed to prevent further deterioration.



NPI Missouri Inc Page 12 of 40


Recommendation

Contact a qualified professional.









3.6.2 Walkways, Patios & Driveways

CRACKING AND SETTLING

SIDEWALKS, GARAGE FLOOR, POOL APRON


Typical cracking and settling are present in the concrete flatwork.

Recommendation

Contact a qualified professional.



NPI Missouri Inc Page 13 of 40



NPI Missouri Inc Page 14 of 40

4: ROOFING

		IN	NI	NP	0
4.1	Coverings	Χ			Χ
4.2	Roof Drainage Systems	Χ			Χ
4.3	Flashings	Χ			Χ
4.4	Skylights, Chimneys & Roof Penetrations	Χ			

IN = Inspected NI = Not Inspected NP = Not Present O = Observations

Information

Inspection Method

Ground, Roof

Roof Drainage Systems: Gutter

Material Aluminum **Roof Type/Style** Gable

Flashings: Material

Aluminum, Plastic, Metal

Roof is well beyond designed life with several damaged and missing shingles. Recommend removal of

Coverings: Material

Asphalt

Observations

4.1.1 Coverings


BEYOND DESIGN LIFE

existing coverings and replacement.

ROOF COVERING



NPI Missouri Inc Page 15 of 40



4.2.1 Roof Drainage Systems

DOWNSPOUTS DRAIN NEAR HOUSE

DOWNSPOUTS



One or more downspouts drain too close to the home's foundation. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement. Recommend adding downspout extensions to drain at least 6 feet from the foundation.

Here is a helpful DIY link and video on draining water flow away from your house.

NPI Missouri Inc Page 16 of 40





4.2.2 Roof Drainage Systems

DAMAGED/FILLED WITH DEBRIS

EXTERIOR

Gutter are filled with debris.

Recommendation

Contact a qualified professional.









4.2.3 Roof Drainage Systems

DAMAGED DOWNSPOUT

FRONT PORCH

Replacement required to the section of damaged downspout.

Recommendation

Contact a qualified professional.




NPI Missouri Inc Page 17 of 40



4.3.1 Flashings

REPLACE





Recommendation

Contact a qualified professional.







NPI Missouri Inc Page 18 of 40



NPI Missouri Inc Page 19 of 40

5: PLUMBING

		IN	NI	NP	0
5.1	Fixtures / Faucets	Χ			
5.2	Drain, Waste, & Vent Systems	Χ			Χ
5.3	Water distribution	Χ			
5.4	Water Heater	Χ			Χ
5.5	Vents, Flues, & Chimneys	Χ			
5.6	Sump Pumps / Sewage Ejectors	Χ			
5.7	Septic System		Χ		

Information

Filters

None

Material - Distribution

Copper

Drain, Waste, & Vent Systems:

Material PVC

Main Fuel Shut-Off (Location)
Electrical Panel, Basement

Material - Water Supply

Copper

Water Heater: Capacity

50 40 Gallons

Main Water Shut-Off Device

(Location)

Basement

Source

Public

Water Heater: Location

Basement



Water Heater: Power Source

Electric

NPI Missouri Inc Page 20 of 40

Water Heater: Manufacturer

Whirlpool









Limitations

Septic System

SCOPE OF WORK

Septic system and well components are not included in this report. See separate septic and well inspection provided by a state certified septic inspector.

Observations

5.2.1 Drain, Waste, & Vent Systems

IMPROPER INSTALLATION - S-TRAP

MASTER SINKS, HALL SINK

S-trap configuration observed. Recommend evaluation and repair by a qualified professional.

Recommendation

Contact a qualified professional.



NPI Missouri Inc Page 21 of 40








5.2.2 Drain, Waste, & Vent Systems

LEAKS

BASEMENT



Recommendation

Contact a qualified professional.





5.4.1 Water Heater

IMPROPER INSTALLATION

BASEMENT



NPI Missouri Inc Page 22 of 40

Electrical wiring is not properly run in secured conduit and relief extensions have not been installed on both units. Recommend qualified plumber evaluate & repair.









NPI Missouri Inc Page 23 of 40

6: ELECTRICAL

		IN	NI	NP	0
6.1	Service Entrance Conductors	Χ			
6.2	Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels	Х			
6.3	Sub-Panel	Χ			Χ
6.4	Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage	Х			Х
6.5	Connected Devices and Fixtures	Χ			
6.6	Polarity and Grounding of Receptacles	Χ			
6.7	GFCI & AFCI	Χ			Χ
6.8	Smoke Detectors		Χ		

IN = Inspected NI = Not Inspected NP = Not Present O = Observations

Information

Branch Wire 15 and 20 AMP Wiring Method Service Entrance Conductors: Electrical Service Conductors Copper Romex Below Ground, Aluminum

Service and Grounding Service and Grounding **Equipment, Main Overcurrent Equipment, Main Overcurrent Device, Main and Distribution** Device. Main and Distribution **Panels: Panel Locations Panels: Panel Capacity** 200 AMP

Basement

Sub-Panel: Panel Locations Sub-Panel: Panel Capacity Basement, Outbuilding

Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution

Panels: Panel Type Circuit Breaker

Sub-Panel: Panel Type Circuit Breaker

Limitations

100 AMP

Smoke Detectors

OPERATION

Recommend all detectors be tested and replaced as required upon occupancy.

Observations

6.3.1 Sub-Panel

PANEL LOCATION



OUTBUILDING

Panel located in the outbuilding bathroom is severe safety hazard. Recommend panel be isolated or moved by a qualified professional for safety purposes.

Recommendation

Contact a qualified professional.

NPI Missouri Inc Page 24 of 40



6.4.1 Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage



EXPOSED ENDS & SPLICES

ATTIC OVER GARAGE

All wire connections & charged wires with exposed ends and splices should be covered in junction boxes for safety. Recommend a qualified electrician correct.





6.4.2 Branch Circuit Conductors, Overcurrent Devices and Compatibility of Their Amperage & Voltage



LOOSE WIRING

BASEMENT

Maintenance recommended to all loose, unsecured, and hanging electrical wires for safety purposes.

NPI Missouri Inc Page 25 of 40



6.7.1 GFCI & AFCI

NO GFCI PROTECTION INSTALLED

GARAGE, KITCHEN, FRONT PORCH, HALL BATHROOM



No GFCI protection present in all required locations. Recommend licensed electrician upgrade by installing ground fault receptacles in all locations.

Here is a link to read about how GFCI receptacles keep you safe.

NPI Missouri Inc Page 26 of 40

7: HEATING

		IN	NI	NP	0
7.1	Heating Equipment	Χ			
7.2	Distribution Systems	Χ			

Information

Heating Equipment: Brand

HVAC

Carrier



Heating Equipment: Energy Source

Electric

Heating Equipment: Filter Type

Disposable

Heating Equipment: Heat Type

Forced Air

Distribution Systems: Ductwork

Non-insulated

NPI Missouri Inc Page 27 of 40

8: AIR CONDITIONING

		IN	NI	NP	0
8.1	Cooling Equipment	Χ			Х
8.2	Distribution System	Χ			

Information

Cooling Equipment: Energy

Source/Type Electric

Cooling Equipment: Brand

Carrier

Distribution System: Configuration

Split





Observations

8.1.1 Cooling Equipment

INSULATION MISSING OR DAMAGED




Recommendations

EXTERIOR

Replacement required to the damaged and missing line insulation.

NPI Missouri Inc Page 28 of 40



NPI Missouri Inc Page 29 of 40

9: INTERIORS

		IN	NI	NP	0
9.1	Walls	Χ			Χ
9.2	Ceilings	Χ			
9.3	Floors	Χ			
9.4	Steps, Stairways & Railings	Χ			
9.5	Countertops & Cabinets	Χ			
9.6	Doors	Χ			
9.7	Windows	Χ			
9.8	Garage Door	Χ			
9.9	Shower Enclosures	Χ			

Information

Ceilings: Ceiling Material

Garage Door: Material

Drywall

Aluminum

Countertops & Cabinets:

CabinetryWood

Garage Door: Type

Up-and-Over


Windows: Window Type

Double-hung, Thermal, Vinyl

NPI Missouri Inc Page 30 of 40

Walls: Wall Material

Drywall



Observations

9.1.1 Walls

DAMAGED FIRE BARRIER



Fire barriers on the garage walls and ceiling have been breached. Fire rated material is not present at the laundry access, drywall has been removed and replaced with plywood, and fire collars or fire caulk is not present at the utility protrusions. Damaged fire barriers are a safety hazard and should be properly secured by a qualified professional.

A Safety Hazards

NPI Missouri Inc Page 31 of 40













9.1.2 Walls

VISIBLE MOLD

GARAGE



Mold is present on finish material in the garage due to high moisture content created by water intrusion. Suspect conditions are due to the downspout discharging at the exterior wall. Recommend removal or treatment by qualified professional for health and safety purposes.

Recommendation

Contact a qualified professional.

NPI Missouri Inc Page 32 of 40





9.1.3 Walls

IMPROPER MATERIAL



Properly rated drywall (green board) has not been installed in the hall bathroom.

Recommendation

Contact a qualified professional.



NPI Missouri Inc Page 33 of 40

10: BUILT-IN APPLIANCES

		IN	NI	NP	0
10.1	Dishwasher	Χ			
10.2	Refrigerator	Χ			
10.3	Range/Oven/Cooktop	Χ			
10.4	Garbage Disposal	Χ			

Information

Range/Oven/Cooktop: Exhaust

Hood Type Re-circulate Range/Oven/Cooktop: Range/Oven Energy Source Electric

NPI Missouri Inc Page 34 of 40

11: INSULATION AND VENTILATION

		IN	NI	NP	0
11.1	Attic Insulation	Χ			
11.2	Ventilation	Χ			
11.3	Exhaust Systems	Χ			Х

NP = Not Present

O = Observations

Information

Dryer Power Source 220 Electric

Dryer Vent Metal (Flex), Rigid PVC **Ventilation: Ventilation Type** Gable Vents, Soffit Vents

Exhaust Systems: Exhaust Fans

Fan with Light

Attic Insulation: Insulation Type

Blown, Fiberglass





Observations

11.3.1 Exhaust Systems

DRYER VENTS INTO ATTIC

ATTIC

Dryer vents into the attic, which can cause moisture and mold. Recommend vent terminate at the exterior.





NPI Missouri Inc Page 35 of 40

12: FIREPLACES AND FUEL-BURNING APPLIANCES

		IN	NI	NP	0
12.1	Fireplaces, Stoves & Inserts	Χ			
12.2	Chimney & Vent Systems	Χ			Χ

Information

Type

Woodstove, Wood

Observations

12.2.1 Chimney & Vent Systems

CLEANING

FAMILY ROOM

Have stove, flue and chimney cleaned.

Recommendation

Contact a qualified professional.





NPI Missouri Inc Page 36 of 40

13: SWIMMING POOL

		IN	NI	NP	0
13.1	Pool Maintenance	Χ			Χ

IN = Inspected

NI = Not Inspected


NP = Not Present

O = Observations

Observations

13.1.1 Pool Maintenance

REQUIRED POOL MAINTENANCE



deteriorated and missing in several areas, typical cracks are present in the concrete apron, apron coating is delaminating at the corner cracks, and the ladder is excessively rusted. Proper grounding is not present at the pump, heater and gas line. Heater was not operational at the time of the inspection. Recommend removing the unused diving board bolts anchored in the apron for safety purposes. Recommend all repairs be performed by a professional pool contractor.

Recommendation

Contact a qualified professional.



NPI Missouri Inc Page 37 of 40



NPI Missouri Inc Page 38 of 40

STANDARDS OF PRACTICE

Structural Components

3. STRUCTURAL COMPONENTS 3.1 The inspector shall: A. inspect structural components including the foundation and framing. B. describe: 1. the methods used to inspect under floor crawlspaces and attics. 2. the foundation. 3. the floor structure. 4. the wall structure. 5. the ceiling structure. 6. the roof structure. 3.2 The inspector is NOT required to: A. provide engineering or architectural services or analysis. B. offer an opinion about the adequacy of structural systems and components. C. enter under floor crawlspace areas that have less than 24 inches of vertical clearance between components and the ground or that have an access opening smaller than 16 inches by 24 inches. D. traverse attic load-bearing components that are concealed by insulation or by other materials.

Exterior

4.1 The inspector shall: A. inspect: 1. wall coverings, flashing, and trim. 2. exterior doors. 3. attached and adjacent decks, balconies, stoops, steps, porches, and their associated railings. 4. eaves, soffits, and fascias where accessible from the ground level. 5. vegetation, grading, surface drainage, and retaining walls that are likely to adversely affect the building. 6. adjacent and entryway walkways, patios, and driveways. B. describe wall coverings. 4.2 The inspector is NOT required to inspect: A. screening, shutters, awnings, and similar seasonal accessories. B. fences, boundary walls, and similar structures. C. geological and soil conditions. D. recreational facilities. E. outbuildings other than garages and carports. F. seawalls, break-walls, and docks. G. erosion control and earth stabilization measures.

Roofing

5.1 The inspector shall: A. inspect: 1. roofing materials. 2. roof drainage systems. 3. flashing. 4. skylights, chimneys, and roof penetrations. B. describe: 1. roofing materials. 2. methods used to inspect the roofing. 5.2 The inspector is NOT required to inspect: A. antennas. B. interiors of vent systems, uses, and chimneys that are not readily accessible. C. other installed accessories.

Plumbing

6.1 The inspector shall: A. inspect: 1. interior water supply and distribution systems including fixtures and faucets. 2. interior drain, waste, and vent systems including fixtures. 3. water heating equipment and hot water supply systems. 4. vent systems, flues, and chimneys. 5. fuel storage and fuel distribution systems. 6. sewage ejectors, sump pumps, and related piping. B. describe: 1. interior water supply, drain, waste, and vent piping materials. 2. water heating equipment including energy source(s). 3. location of main water and fuel shut-off valves. 6.2 The inspector is NOT required to: A. inspect: 1. clothes washing machine connections. 2. interiors of vent systems, flues, and chimneys that are not readily accessible. 3. wells, well pumps, and water storage related equipment. 4. water conditioning systems. 5. solar, geothermal, and other renewable energy water heating systems. 6. manual and automatic re-extinguishing and sprinkler systems and landscape irrigation systems. 7. septic and other sewage disposal systems. B. determine: 1. whether water supply and sewage disposal are public or private. 2. water quality. 3. the adequacy of combustion air components. C. measure water supply low and pressure, and well water quantity. D. fill shower pans and fixtures to test for leaks.

Electrical

7.1 The inspector shall: A. inspect: 1. service drop. 2. service entrance conductors, cables, and raceways. 3. service equipment and main disconnects. 4. service grounding. 5. interior components of service panels and subpanels. 6. conductors. 7. overcurrent protection devices. 8. a representative number of installed lighting fixtures, switches, and receptacles. 9. ground fault circuit interrupters and arc fault circuit interrupters. B. describe: 1. amperage rating of the service. 2. location of main disconnect(s) and subpanels. 3. presence or absence of smoke alarms and carbon monoxide alarms. 4. the predominant branch circuit wiring method. 7.2 The inspector is NOT required to: A. inspect: 1. remote control devices. 2. or test smoke and carbon monoxide alarms, security systems, and other signaling and warning devices. 3. low voltage wiring systems and components. 4. ancillary wiring systems and components not a part of the primary electrical power distribution system. 5. solar, geothermal, wind, and other renewable energy systems. B. measure amperage, voltage, and impedance. C. determine the age and type of smoke alarms and carbon monoxide alarms.

Heating

8.1 The inspector shall: A. open readily openable access panels. B. inspect: 1. installed heating equipment. 2. vent systems, uses, and chimneys. 3. distribution systems. C. describe: 1. energy source(s). 2. heating systems. 8.2 The inspector is NOT required to: A. inspect: 1. interiors of vent systems, uses, and chimneys that are not readily accessible. 2. heat exchangers. 3. humidifiers and dehumidifiers. 4. electric air cleaning and sanitizing devices. 5. heating systems using ground-source, water-source, solar, and renewable energy technologies. 6. heat-recovery and similar whole-house mechanical ventilation systems. B. determine: 1. heat supply adequacy and distribution balance. 2. the adequacy of combustion air components.

Air Conditioning

NPI Missouri Inc Page 39 of 40

9.1 The inspector shall: A. open readily openable access panels. B. inspect: 1. central and permanently installed cooling equipment. 2. distribution systems. C. describe: 1. energy source(s). 2. cooling systems. 9.2 The inspector is NOT required to: A. inspect electric air cleaning and sanitizing devices. B. determine cooling supply adequacy and distribution balance. C. inspect cooling units that are not permanently installed or that are installed in windows. D. inspect cooling systems using ground source, water source, solar, and renewable energy technologies.

Interiors

10.1 The inspector shall inspect: A. walls, ceilings, and floors. B. steps, stairways, and railings. C. countertops and a representative number of installed cabinets. D. a representative number of doors and windows. E. garage vehicle doors and garage vehicle door operators. F. installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders by using normal operating controls to activate the primary function. 10.2 The inspector is NOT required to inspect: A. paint, wallpaper, and other finish treatments. B. floor coverings. C. window treatments. D. coatings on and the hermetic seals between panes of window glass. E. central vacuum systems. F. recreational facilities. G. installed and free-standing kitchen and laundry appliances not listed in Section 10.1.F. H. appliance thermostats including their calibration, adequacy of heating elements, self cleaning oven cycles, indicator lights, door seals, timers, clocks, timed features, and other specialized features of the appliance. I. operate, or confirm the operation of every control and feature of an inspected appliance.

Built-in Appliances

10.1 The inspector shall inspect: F. installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders by using normal operating controls to activate the primary function. 10.2 The inspector is NOT required to inspect: G. installed and free-standing kitchen and laundry appliances not listed in Section 10.1.F. H. appliance thermostats including their calibration, adequacy of heating elements, self cleaning oven cycles, indicator lights, door seals, timers, clocks, timed features, and other specialized features of the appliance. I. operate, or con rm the operation of every control and feature of an inspected appliance.

Insulation and Ventilation

11.1 The inspector shall: A. inspect: 1. insulation and vapor retarders in unfinished spaces. 2. ventilation of attics and foundation areas. 3. kitchen, bathroom, laundry, and similar exhaust systems. 4. clothes dryer exhaust systems. B. describe: 1. insulation and vapor retarders in unfinished spaces. 2. absence of insulation in unfinished spaces at conditioned surfaces. 11.2 The inspector is NOT required to disturb insulation.

Fireplaces and Fuel-Burning Appliances

12.1 The inspector shall: A. inspect: 1. fuel-burning replaces, stoves, and replace inserts. 2. fuel-burning accessories installed in replaces. 3. chimneys and vent systems. B. describe systems and components listed in 12.1.A.1 and .2. 12.2 The inspector is NOT required to: A. inspect: 1. interiors of vent systems, uses, and chimneys that are not readily accessible. 2. fire screens and doors. 3. seals and gaskets. 4. automatic fuel feed devices. 5. mantles and replace surrounds. 6. combustion air components and to determine their adequacy. 7. heat distribution assists (gravity fed and fan assisted). 8. fuel-burning replaces and appliances located outside the inspected structures. B. determine draft characteristics. C. move fireplace inserts and stoves or firebox contents.

NPI Missouri Inc Page 40 of 40